① Generic intalation rack cart 2/3 shelves

1.Lay the front door frame on the working table.
2.Fix both left and right side frames on front door frames by M4 self-tapping screws.
3.Fix the rear door frame by M4 self-tapping screws.







②



1.Fix the top and bottom covers on the
frames by M4 self-tapping screws.



③



1.Fix the 4 castors on the four sides of the
base by M8 tapping screws.

④

8.guiding rail bracket



1.Install guiding rail brackets into
cabinets by M5 self-tapping screws.

⑤

1.Insert the shelf with guiding rail
and clapboard into guiding rail bracket.

9.clapboard

10.shelf

⑥

1.Fix the PDU bracket on rear door frame by
M5 self-tapping screws.
2.Install the PDU to PDU brackets.

9.Power supply controlling PDU

11.PDU bracket 1

12.PDU bracket 2

13.Charging PDU

⑦



latch

14.left and right door

1.Put rotating shafts on bottom holes of door frames.
2.Install the left and right door, fix the top by latches.

15.rotating shaft

⑧

1.remove the plastic cover of handle.
2.Fix the handle on the top by M10 hexagon bolt.
3.Cover the plastic cover.

16.Handle